Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW0959/1

Work Order Type: Weatherization

Audit Name: 12012NW0959

CLIENT INFORMATION

Client Name: Address:

Client ID: 12012NW0959

Alt. Client ID:

AGENCY INFORMATION

Agency: Northwest Tn. Economic Development Council Agency Phone: (731) 364-3228

Address: 231 South Wilson St. **Fax:** (731) 364-5029

Dresden, TN 38225-1312 Email Address:

Agency Contact: Woods, Max Work Phone: (731) 286-0332

Cell Phone: (731) 676-1414

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Measures

	ulk Windows (12)			Componen	ts			Inspected
Comment Silicon	ne							
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 2 Do	or #1			Componen	ts			Inspected
Comment Door #	44 \\\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			•				
	•							
	Door Shoe							
	•			Estimatos	,		Actual	
# Material / Labor	Door Shoe Caulk	Unite	Oftv	Estimated	 -	Ofv	Actual	Total
# Material / Labor	Door Shoe Caulk Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
	Door Shoe Caulk	<i>Units</i> Each	Qty 1		 -	Qty		Total
	Door Shoe Caulk Description / Comment				 -	Qty		Total
10 Unspecified	Door Shoe Caulk Description / Comment				 -	Qty		Total
10 Unspecified	Door Shoe Caulk Description / Comment				 -	Qty		Total
10 Unspecified	Door Shoe Caulk Description / Comment	Each	1		 -			Total
10 Unspecified Other Detail	Door Shoe Caulk Description / Comment	Each	1	Unit Cost	 -		Unit Cost	Total
10 Unspecified	Door Shoe Caulk Description / Comment	Each	1	Unit Cost	 -		Unit Cost	Total
10 Unspecified Other Detail	Door Shoe Caulk Description / Comment	Each	1	Unit Cost	 -		Unit Cost	Total
10 Unspecified Other Detail	Door Shoe Caulk Description / Comment	Each	1	Unit Cost	 -		Unit Cost	Total

Measure 3 Door #2				Componen	ts			Inspected
Comment Door #	Z Oddik			Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail] [7		
] [
			Measur	e Sub Total:]	Sub Total:	
Field Notes:								
Measure 4 Doo	or #3			Componen	ts			Inspected
Comment Door #	Threshold							
	Caulk			Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail				1		7		
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								

Report Run On: 5/15/2010

Measure 5 Do	or #4			Componen	ts			Inspected
Comment Door #	4 Caulk							
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								
	stic/Seal Duct Boots and	d Fix		Componen	ts			Inspected
Pro Comment Mastic Came		n Back Be		had very hid nd tape sear	gh readin ns. Ched			Inspected
Comment Mastic Came other o	oblems All Duct Boots (7) Duct in loose from boot. Re-attacennections and joints	n Back Be ch and sec	cure ar	had very high and tape sear Estimated	gh readin ns. Ched	k all	Actual	
Pro Comment Mastic Came other of	All Duct Boots (7) Duct in loose from boot. Re-attace connections and joints Description / Comment	n Back Be ch and sed <i>Unit</i> s	Qty	had very hid nd tape sear	gh readin ns. Ched			Inspected
Pro Comment Mastic Came other of	oblems All Duct Boots (7) Duct in loose from boot. Re-attacennections and joints	n Back Be ch and sec	cure ar	had very high and tape sear Estimated	gh readin ns. Ched	k all	Actual	
Pro Comment Mastic Came other of	All Duct Boots (7) Duct in loose from boot. Re-attace connections and joints Description / Comment	n Back Be ch and sed <i>Unit</i> s	Qty	had very high and tape sear Estimated	gh readin ns. Ched	k all	Actual	
Pro Comment Mastic Came other of # Material / Labor 10 Unspecified	All Duct Boots (7) Duct in loose from boot. Re-attace connections and joints Description / Comment	n Back Be ch and sed <i>Unit</i> s	Qty	had very high and tape sear Estimated	gh readin ns. Ched	k all	Actual	
Pro Comment Mastic Came other of # Material / Labor 10 Unspecified	All Duct Boots (7) Duct in loose from boot. Re-attace connections and joints Description / Comment	n Back Be ch and sed <i>Unit</i> s	Qty	had very high and tape sear Estimated	gh readin ns. Ched	k all	Actual	
Pro Comment Mastic Came other of # Material / Labor 10 Unspecified	All Duct Boots (7) Duct in loose from boot. Re-attace connections and joints Description / Comment	n Back Be ch and sec <i>Units</i> Each	Qty 1	had very high and tape sear Estimated	gh readin ns. Ched	Qty	Actual	
Pro Comment Mastic Came other of # Material / Labor 10 Unspecified	All Duct Boots (7) Duct in loose from boot. Re-attace connections and joints Description / Comment	n Back Be ch and sec <i>Units</i> Each	Qty 1	had very highed tape sear	gh readin ns. Ched	Qty	Actual Unit Cost	
Comment Mastic Came other of # Material / Labor 10 Unspecified Other Detail	All Duct Boots (7) Duct in loose from boot. Re-attace connections and joints Description / Comment	n Back Be ch and sec <i>Units</i> Each	Qty 1	had very highed tape sear	gh readin ns. Ched	Qty	Actual Unit Cost	

Comment	grade Attic Access			Componen	ts			Inspected
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
Foam E k	Crown thru out house Bathroom Plumbing (2) Kitchen Plumbing oam Head of tub (2) Sea							
Foam h	ole in exterior wall (Back	Bedroom)	Appr	ox 3" Loa H	ome			
Foam h	nole in exterior wall (Back	Bedroom)	Appr	ox 3" Log H <i>Estimated</i>			Actual	
	nole in exterior wall (Back Description / Comment	Bedroom) <i>Units</i>	Appr Qty	_		Qty	Actual Unit Cost	Total
# Material / Labor	·	•		Estimated	<u> </u>	Qty		Total
# Material / Labor 0 Miscellaneous	Description / Comment	Units	Qty	Estimated	<u> </u>	Qty		Total
# Material / Labor 0 Miscellaneous Supplies	Description / Comment	Units	Qty	Estimated	<u> </u>	Qty		Total
# Material / Labor 0 Miscellaneous Supplies	Description / Comment	Units	Qty	Estimated	<u> </u>	Qty		Total
# Material / Labor 0 Miscellaneous Supplies	Description / Comment	Units Each	Qty 1	Estimated	<u> </u>			Total
# Material / Labor 0 Miscellaneous Supplies	Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Unit Cost	Total
# Material / Labor 0 Miscellaneous Supplies Other Detail	Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Unit Cost	Total

Alt. Client ID:

Report Run On: 5/15/2010

	Measure 9 DWI Comment	H Pipe Insulation			Componer				Inspected
4	Matarial / Labor	December 10 mm and	Unita		Estimated			Actual	Total
	Material / Labor	Description / Comment	Units 	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
(Other Detail						1		
L									
				Measur	e Sub Total:] ,	Sub Total:	
	Measure 10 DWI	H Tank Insulation t Water Heater			Componer				Inspected
C	Comment Gas Ho	t Water Heater			Estimated	d		Actual	
C			<i>Units</i> Each	Qty 1	-		Qty		Inspected Total
C #	Comment Gas Hoo Material / Labor Hot Water	t Water Heater Description / Comment		Qty	Estimated	d	Qty	Actual	
6 # 1	Comment Gas Ho Material / Labor Hot Water Equipment	t Water Heater Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	d	Qty	Actual	
6 # 1	Comment Gas Hor Material / Labor Hot Water Equipment Labor	t Water Heater Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	d	Qty	Actual	
6 # 1	Comment Gas Hor Material / Labor Hot Water Equipment Labor	t Water Heater Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	d	Qty	Actual	
t 1	Comment Gas Hor Material / Labor Hot Water Equipment Labor	t Water Heater Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	d		Actual	

Alt. Client ID:

	<i>Measur</i> e 11 Floo	r Ins. R-19			Componen	<i>ts</i> F1,F2			Inspected
C	Comment 16" Cen	ters Entire home							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1250					
2	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	152					
(Other Detail						1		
			ı	Measure	e Sub Total:			Sub Total:	
	Measure 12 CO N	Monitor is Needed			Componen	ts			Inspected
		Monitor is Needed			Componen Estimated			Actual	Inspected
C		Monitor is Needed Description / Comment	Units	Qty	-		Qty		Inspected
C	Comment	Description / Comment	<i>Units</i> Each		Estimated	1	Qty	Actual	
*	Comment Material / Labor Health and Safety	Description / Comment		Qty	Estimated	1	Qty	Actual	
t 1	Comment Material / Labor Health and Safety Items	Description / Comment CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
t 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
t 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
t 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated	1		Actual	
t 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	

	Measure 13 Fix I	mproper Venting (Cloth	es Dryer)		Componen	ts			Inspected
C	Comment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
		all Bathroom Exhaust F non-working bath exhaun							Inspected
C	Comment Replace Hall Batl	non-working bath exhau	ust and ve	nt thru	roof.	,	Otv	Actual	
<i>C</i>	comment Replace	non-working bath exhaund h			roof.		Qty		Inspected
C #	Comment Replace Hall Batl Material / Labor Health and Safety	non-working bath exhaund h	ust and ve <i>Unit</i> s	nt thru	roof.	,	Qty	Actual	
C # 1	Comment Replace Hall Bath Material / Labor Health and Safety Items	non-working bath exhaund h Description / Comment Bathroom exhaust fan	ust and ve <i>Units</i> Each	Oty 1	roof.	,	Qty	Actual	
C # 1	Comment Replace Hall Bath Material / Labor Health and Safety Items Labor	non-working bath exhaund h Description / Comment Bathroom exhaust fan	ust and ve <i>Units</i> Each	Oty 1	roof.	,	Qty	Actual	
C # 1	Comment Replace Hall Bath Material / Labor Health and Safety Items Labor	non-working bath exhaund h Description / Comment Bathroom exhaust fan	ust and ve <i>Units</i> Each	Oty 1	roof.	,	Qty	Actual	
C # 1	Comment Replace Hall Bath Material / Labor Health and Safety Items Labor	non-working bath exhaund h Description / Comment Bathroom exhaust fan	Units Each Hour	Qty 1	roof.	,		Actual	

DOE Weatherization Assistant Version 8.5.0 Page 8 of 10

Report Run On: 5/15/2010

-	Measure 15 Insta Bath	all Bathroom Exhaust F	an Mast	er	Componen	ts		ı	Inspected
C	omment Install B	ath exhaust in master ba	ath and ve	nt thru	roof.				
					Estimated	1		Actual	
#	Material / Labor	Description / Comment Units Qty Unit Cost Tot				Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Measure 16 Insta	all Cover on Outlet in M	aster Bat	n	Componen	ts		,	Inspected
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
C	Other Detail								
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:				L		-		

Measure 17 Pres	sureRelief Piping Need	ded		Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Pressure relief piping	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
] []		
				- Out T-4-1] []	Sub Total:	
			Measur	e Sub Total:			Sub Total:	
(Bas	or Barrier Needed sement/Crawlspace) House Approx 1250 sq	ı ft		Componen	ts			Inspected
Common Cinginal	7. Pp. 10. 1200 00	ļ.·· · ·		Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1 [
			Measur	e Sub Total:			Sub Total:	
Field Notes:		West 0	vdo: 0:	and Todal		0	d Total:	
		vvork Or	der Gra	nd Total:		Gran	d Total:	